

신김포-신파주

Station(m)	균열	누수	파손 및 손상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	결함점수 합계	결함지수
0~20	6.00	0.00	0.00	0.00	0.00	0.01	0.01	0.00	x	6	0.176
20~40	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
40~60	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
60~80	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
80~100	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	0	6	0.176
100~120	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
120~140	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
140~160	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
160~180	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
180~200	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
200~220	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
220~240	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
240~260	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
260~280	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
280~300	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
300~320	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	0	6	0.176
320~340	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
340~360	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
360~380	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
380~400	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
400~420	6.00	0.01	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
420~440	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
440~460	6.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
460~480	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
480~500	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
500~520	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
520~540	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
540~560	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
560~580	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
580~600	6.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
600~620	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
620~640	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
640~660	6.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
660~680	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
680~700	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
700~720	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
720~740	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
740~760	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
760~780	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
780~800	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
800~820	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
820~840	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
840~860	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
860~880	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
880~900	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
900~920	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
920~940	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
940~960	6.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
960~980	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
980~1000	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1000~1020	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1020~1040	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
Station(m)	균열	누수	파손 및 손상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	결함점수 합계	결함지수

1040~1060	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
1060~1080	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1080~1100	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1100~1120	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1120~1140	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1140~1160	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1160~1180	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1180~1200	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1200~1220	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1220~1240	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1240~1260	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1260~1280	6.00	0.00	0.00	0.01	0.00	0.01	0.00	0.00	x	6	0.176
1280~1300	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1300~1320	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1320~1340	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1340~1360	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1360~1380	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
1380~1400	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1400~1420	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1420~1440	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
1440~1460	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1460~1480	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
1480~1500	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1500~1520	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1520~1540	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1540~1560	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	0	6	0.176
1560~1580	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1580~1600	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1600~1620	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1620~1640	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1640~1660	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1660~1680	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1680~1700	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
1700~1720	6.00	0.01	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1720~1740	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1740~1760	6.00	0.00	0.00	0.00	0.00	1.00	0.00	0.00	x	7	0.206
1760~1780	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1780~1800	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1800~1820	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1820~1840	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176

1840~1860	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1860~1880	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1880~1900	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1900~1920	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	0	6	0.176
1920~1940	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
1940~1960	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1960~1980	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
1980~2000	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2000~2020	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	0	0.000
2020~2040	5.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0	5	0.147
2040~2060	6.00	0.00	0.00	0.00	0.00	0.01	0.00	0.00	x	6	0.176
2060~2080	4.00	0.00	1.00	0.00	0.00	0.01	0.00	0.00	x	5	0.147
2080~2100	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
2100~2120	6.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	x	6	0.176
Station(m)	균열	누수	파손 및손상	박리	충분리 및박락	백태	재료분리	철근노출	탄산화	결함점수합계	결함지수
평 균	5.9	0.0	0.0	0.0	0.0	0.1	0.0	0.0	0.0	6.0	0.176

Station(m)	균열	누수	파손 및손상	박리	충분리 및박락	백태	재료분리	철근노출	탄산화	상태평가결과
0~20	c	a	a	a	a	b	b	a	x	b
20~40	c	a	a	a	a	c	a	a	x	b
40~60	c	a	a	a	a	b	a	a	x	b
60~80	c	a	a	a	a	b	a	a	x	b
80~100	c	a	a	a	a	b	a	a	a	b
100~120	c	a	a	a	a	b	a	a	x	b
120~140	c	a	a	a	a	b	a	a	x	b
140~160	c	a	a	a	a	a	a	a	x	b
160~180	c	a	a	a	a	b	a	a	x	b
180~200	c	a	a	a	a	b	a	a	x	b
200~220	c	a	a	a	a	b	a	a	x	b
220~240	c	a	a	a	a	b	a	a	x	b
240~260	c	a	a	a	a	b	a	a	x	b
260~280	c	a	a	a	a	b	a	a	x	b
280~300	c	a	a	a	a	b	a	a	x	b
300~320	c	a	a	a	a	b	a	a	a	b
320~340	c	a	a	a	a	b	a	a	x	b
340~360	c	a	a	a	a	b	a	a	x	b
360~380	c	a	a	a	a	b	a	a	x	b
380~400	c	a	a	a	a	b	a	a	x	b
400~420	c	a	a	a	a	c	a	a	x	b
420~440	c	a	a	a	a	b	a	a	x	b
440~460	c	a	a	a	a	b	a	a	x	b
460~480	c	a	a	a	a	b	a	a	x	b
480~500	c	a	a	a	a	b	a	a	x	b
500~520	c	a	a	a	a	b	a	a	x	b
520~540	c	a	a	a	a	b	a	a	x	b
540~560	c	a	a	a	a	b	a	a	x	b
560~580	c	a	a	a	a	b	a	a	x	b

580~600	c	a	a	a	a	b	a	a	x	b
600~620	c	a	a	a	a	b	a	a	x	b
620~640	c	a	a	a	a	b	a	a	x	b
640~660	c	a	a	a	a	b	a	a	x	b
660~680	c	a	a	a	a	b	a	a	x	b
680~700	c	a	a	a	a	c	a	a	x	b
700~720	c	a	a	a	a	b	a	a	x	b
720~740	c	a	a	a	a	b	a	a	x	b
740~760	c	a	a	a	a	b	a	a	x	b
760~780	c	a	a	a	a	b	a	a	x	b
780~800	c	a	a	a	a	b	a	a	x	b
800~820	c	a	a	a	a	b	a	a	x	b
820~840	c	a	a	a	a	b	a	a	x	b
840~860	c	a	a	a	a	b	a	a	x	b
860~880	c	a	a	a	a	b	a	a	x	b
880~900	c	a	a	a	a	b	a	a	x	b
900~920	c	a	a	a	a	b	a	a	x	b
Station(m)	균열	누수	파손 및 손 상	박리	층분리 및 박락	백태	재료 분리	철근 노출	탄산화	상태평가 결과
920~940	c	a	a	a	a	b	a	a	x	b
940~960	c	a	a	a	a	b	a	a	x	b
960~980	c	a	a	a	a	b	a	a	x	b
980~1000	c	a	a	a	a	b	a	a	x	b
1000~1020	c	a	a	a	a	b	a	a	x	b
1020~1040	c	a	a	a	a	a	a	a	x	b
1040~1060	c	a	a	a	a	c	a	a	x	b
1060~1080	c	a	a	a	a	b	a	a	x	b
1080~1100	c	a	a	a	a	a	a	a	x	b
1100~1120	c	a	a	a	a	b	a	a	x	b
1120~1140	c	a	a	a	a	b	a	a	x	b
1140~1160	c	a	a	a	a	b	a	a	x	b
1160~1180	c	a	a	a	a	a	a	a	x	b
1180~1200	c	a	a	a	a	a	a	a	x	b
1200~1220	c	a	a	a	a	b	a	a	x	b
1220~1240	c	a	a	a	a	a	a	a	x	b
1240~1260	c	a	a	a	a	b	a	a	x	b
1260~1280	c	a	a	b	a	b	a	a	x	b
1280~1300	c	a	a	a	a	a	a	a	x	b
1300~1320	c	a	a	a	a	b	a	a	x	b
1320~1340	c	a	a	a	a	a	a	a	x	b
1340~1360	c	a	a	a	a	a	a	a	x	b
1360~1380	c	a	a	a	a	c	a	a	x	b
1380~1400	c	a	a	a	a	b	a	a	x	b
1400~1420	c	a	a	a	a	b	a	a	x	b
1420~1440	c	a	a	a	a	c	a	a	x	b
1440~1460	c	a	a	a	a	b	a	a	x	b
1460~1480	c	a	a	a	a	c	a	a	x	b

1480~1500	c	a	a	a	a	b	a	a	x	b
1500~1520	c	a	a	a	a	b	a	a	x	b
1520~1540	c	a	a	a	a	b	a	a	x	b
1540~1560	c	a	a	a	a	b	a	a	a	b
1560~1580	c	a	a	a	a	b	a	a	x	b
1580~1600	c	a	a	a	a	b	a	a	x	b
1600~1620	c	a	a	a	a	b	a	a	x	b
1620~1640	c	a	a	a	a	b	a	a	x	b
1640~1660	c	a	a	a	a	b	a	a	x	b
1660~1680	c	a	a	a	a	b	a	a	x	b
1680~1700	c	a	a	a	a	c	a	a	x	b
1700~1720	c	a	a	a	a	b	a	a	x	b
1720~1740	c	a	a	a	a	b	a	a	x	b
1740~1760	c	a	a	a	a	c	a	a	x	b
1760~1780	c	a	a	a	a	b	a	a	x	b
1780~1800	c	a	a	a	a	b	a	a	x	b
1800~1820	c	a	a	a	a	b	a	a	x	b
1820~1840	c	a	a	a	a	a	a	a	x	b
1840~1860	c	a	a	a	a	b	a	a	x	b
1860~1880	c	a	a	a	a	b	a	a	x	b
1880~1900	c	a	a	a	a	b	a	a	x	b
1900~1920	c	a	a	a	a	b	a	a	a	b
1920~1940	c	a	a	a	a	b	a	a	x	b
1940~1960	c	a	a	a	a	a	a	a	x	b
1960~1980	c	a	a	a	a	a	a	a	x	b
1980~2000	a	a	a	a	a	a	a	a	x	a
Station(m)	균열	누수	파손 및 손상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	상태평가 결과
2000~2020	a	a	a	a	a	a	a	a	x	a
2020~2040	b	a	a	a	a	a	a	a	a	a
2040~2060	c	a	a	a	a	b	a	a	x	b
2060~2080	b	a	c	a	a	b	a	a	x	a
2080~2100	c	a	a	a	a	a	a	a	x	b
2100~2120	c	a	a	a	a	a	a	a	x	b
평 균	b	a	a	a	a	b	a	a	a	b

항목	균열	누수	파손 및 손상	박리	충분리 및 박락	백태	재료 분리	철근 노출	탄산화	합계
결합 점수	5.9	0.0	0.0	0.0	0.0	0.1	0.0	0.0	0.0	6.0

결함지수	0.176
상태평가 결과	b