


$\frac{1}{2}$
 $\frac{1}{2}$
 $\frac{1}{2}$
 $\frac{1}{2}$

안겨 박스 외관조사만도

전면부

0517



十
 卅
 百
 千

하천방류

KEY PLAN

가
0
매
0
K
계
표

손상물량 집계표		손상현황					
NO	손상내용	폭 (m,mm)	길이 (m)	깊이 (m)	개수 (EA)	물량 단위	결함 상태
	종류						
1	수평재 파손	-	1.6	-	1.0	1.6	m b
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							

三、









작품

천정면

아카이브

--	--	--	--

모
로



후생연령

이제 오

한글
한글
한글
한글
한글
한글

05 10 00

2019년 하반기 지방하천 배수문 정밀점검 요약

100

임겨 박스 외관조사만도

NONE SCALE

점검기간

20

2019. 11. 19 ~ 2020. 01. 26