






한글
한자
한글
한자

수민체외권자만

KEY PLAN















三
二
一



손상물량집계표									
NO		손상내용	손상현황						
	종류	폭 (m,mm)	길이 (m)	깊이 (m)	개소 (EA)	물량	단위	결함 상태	
1	헐들 표면부식	0.1	1.0	-	1.0	1.0	m²	b	
2									
3									
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									

모



한양대학교

이요하

구
하
하
하
하
하

요 요 요

2019년 하반기 지방하천 배수문 정밀점검 영역

두면면
출처

수문 본체 외관조사망도
NONE SCA

노면표지
점검기

19
2019. 11. 19 ~ 2020. 01. 26