



손상 위치

수문 본체 외관조사망도


※배면과 손상부를 제외한 부재 표면보수 할 것. 평면도




좌측면도




정면도



우측면도










배면도



KEY PLAN

손상물량 집계표									
손상내용			손상현황						
NO	종류	폭 (m,mm)	길이 (m)	깊이 (m)	개소 (EA)	물량 단위	결함 상태	b	c
1	헨드브레이크파손	-	-	-	1.0	1.0			
2	표면부식	2.0	3.0	-	1.0	6.0	m ²	b	
3	표면부식	0.5	2.0	-	2.0	2.0	m ²	c	
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									

범례																					
발주처	화성시청	공역	주식회사성본	공역명	2019년 하반기 지방하천 배수문 정밀점검 공역									도면명		수문 본체 외관조사망도		도면번호		34	
작성		시		명										축척		NONE SCALE		점검기간		2019. 11. 19 ~ 2020. 01. 26	