



번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	1층		2층
	3층		4층
	5층		6층
	7층		8층
	9층		10층
	11층		12층
	13층		14층
	15층		16층
	17층		18층
	19층		20층
	21층		22층
	23층		24층
	25층		26층
	27층		28층
	29층		30층
	31층		32층
	33층		34층
	35층		36층
	37층		38층
	39층		40층
	41층		42층
	43층		44층
	45층		46층
	47층		48층
	49층		50층
	51층		52층
	53층		54층
	55층		56층
	57층		58층
	59층		60층
	61층		62층
	63층		64층
	65층		66




번호	위치	손상내용	손상물량					비고
			쪽	길이	개소	단위	수량	
1	거더내부	청경등덜개탈락	-	-	1	ea	1.0	
2	거더내부	청경등덜개탈락	-	-	1	ea	1.0	
3	거더내부	청경등덜개파손	-	-	1	ea	1.0	
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	군열		별대, 별부
	파산, 탈락, 박리, 박락		별관, 총부리
	절근노출		부식
	채수		채수구막힘
	이물질 퇴적		변형
	망상군열		열화
	재료분리		보수
	누수, 습윤부		기타



번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1	거터내부	점결등압개할악	-	-	2	ea	2.0	
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 탈락, 박리, 박락		틀림, 총분리
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타



번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1	교대	누수흔적	0.2	1.0	1	㎡	0.2	
2	교대	균열	0.2	0.8	1	m	0.8	
3	교대	파손	12.0	0.1	1	㎡	1.2	
4	교대	누수흔적	0.2	1.0	1	㎡	0.2	
5	교대	누수흔적	1.0	4.0	1	㎡	4.0	
6	선속이음	흙음재 탈락	-	2.0	1	m	2.0	
7	방청장치	방청콘크리트균열	0.1	0.2	4	m	0.8	
8	교대	누수흔적	5.0	2.0	1	㎡	10.0	
9	교대	누수흔적	7.0	2.0	1	㎡	14.0	
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		백대, 결로
	파손, 탈락, 박리, 박락		흙음재, 흙분리
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타

용역사

(주)명성엔지니어링

발주처

대구 동부순환도로 (주)

용역명

2022년도 하반기 정기안전점검 기술용역

구간


연호고가교

위치

교대 A1,A2

N

067



용역사

(주)명성엔지니어링

발주처

대구 동부순환도로 (주)

용역명

2022년도 하반기 정기안전점검 기술용역

구간

연호고가교

위치

교각P5

N

072

