



No.6(2) 영인면 아산로 1233번길 12



정면




[결함물량표]




No	손상내용	결함규모				사진 번호	비고
		폭	길이	단위	개소		
1	수직균열	0.3	0.50	m	1	1	
2	수직균열	1.0	1.00	m	1	2	
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

*NONE : 균열폭의 단위는 mm임.

[손상범례]



No.6(2) 영인면 아산로 1233번길 12




[결함물량표]

No	손상내용	결함규모				사진 번호	비고
		폭	길이	단위	개소		
1	파손	1.00	1.00	m²	1	3	
2	파손	1.00	1.00	m²	1	4	
3	수평균열	0.2	3.00	m	1	5	
4	수직균열	0.3	3.00	m	1	6	
5	수평균열	0.3	3.00	m	1	7	
6	이격	-	2.50	m	1	8	T=1.0cm
7	수직균열	0.1	1.00	m	1	9	
8	수직균열	0.2	1.00	m	1	10	
9	수평균열	0.3	0.50	m	1	11	
10	수평균열	0.2	0.50	m	3	12	
11	수직균열	0.3	2.50	m	1	13	
12	경사균열	0.1	0.50	m	1	14	
13	망상균열	1.00	1.00	m²	1	15	
14	들뜸	0.20	0.40	m²	1	16	
15	들뜸	0.20	2.00	m²	1	17	
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

*NONE : 균열폭의 단위는 mm임.

[손상범례]



발주처

(주)대림산업

안전진단기관

명성엔지니어링

용역명

서해선(홍선~송산) 복선전철 제5공구 건설공사 사후현황 용역[공사후]




도면명

좌측면

도면번호

002

No.6(2) 영인면 아산로 1233번길 12






[결함물량표]

No	손상내용	결함규모				사진 번호	비고
		폭	길이	단위	개소		
1	수직균열	0.3	0.30	m	1	18	
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

*NONE : 균열폭의 단위는 mm임.

[손상범례]

No.6(2) 영인면 아산로 1233번길 12



[결함물량표]

No	손상내용	결함규모				사진 번호	비고
		폭	길이	단위	개소		
1	상태현황	-	-	-	-	19	
2	상태현황	-	-	-	-	20	
3	상태현황	-	-	-	-	21	
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

*NONE : 균열폭의 단위는 mm임.

[손상범례]
