



11. 콘크리트옹벽(9공구)

10:9공구 콘크리트 옹벽(1)

→ 대구



SECTION

[illegible]

용역명	2016년 상반기 시설물 정기점검 용역
과업기간	2016. 04. 18 ~ 2016. 06. 30
발주처	 신대구부산고속도로주식회사
용역사	(주)위드이앤오
도면번호	001

10:9공구 콘크리트 옹벽(2)

손상 현황 표

[illegible]

주) 손상의 폭과 길이는 m 이며, 단 균열의 폭은 mm 임

KEY PLAN



The key plan shows a site bounded by a road to the north and a road to the east. The site is divided into several areas, with the proposed development area shaded in grey. The site is located adjacent to a road that runs north-south. The surrounding area includes existing roads, fields, and a river. The plan also shows the location of the proposed development area relative to the surrounding roads and land use.

SECTION

The diagram shows a cross-section of a bridge structure. On the left is a rectangular pier. To its right is a larger abutment structure. The abutment has a vertical stem and a wider base. The top of the stem is labeled '1:10.00'. The top of the abutment is labeled '1:1.5'. The ground level on the right is indicated by a line with diagonal hatching. The ground level on the left is indicated by a line with diagonal hatching.

용역명	2016년 상반기 시설물 정기점검 용역
과업기간	2016. 04. 18 ~ 2016. 06. 30
발주처	 신대구부산고속도로주식회사
용역사	(주)위드이앤오
도면번호	002