

11. 도로용벽-송정IC R-B(sta.0+445~0+735) 상태평가 결과표

SPAN NO.	침하	계획 선형 오차	활동	파손 · 손상	균열	마모 · 침식	바리	바 락 · 충분리	탄 산 화	염 화 물	백 태	배수 공	주변영향인자			결합 점수 합계	평가단 위 결합 지수	평가 단위 평가 등급	
													배수 시설	사면조사					
														사면 구배	낙석 흔적				침 출수
S1	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0.01	a
S2	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0.01	a
S3	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0.01	a
S4	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
S5	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
S6	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
S7	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
S8	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
S9	0	0	0	0	4	0	0	0	0	0	0	0	0	0	0	0	4	0.05	a
S10	0	0	0	1	4	0	0	0	0	0	0	0	0	0	0	0	5	0.07	a
S11	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
S12	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
S13	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
S14	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
S15	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	a
평균	0	0	0	0.27	0.53	0	0	0	0	0	0	0	0	0	0	0	0.80	0.01	a

상태평가등급	A
--------	---

■ 결함지수 평균점수 범위가 $0.00 \leq F < 0.15$ 이므로 상태평가등급은“A등급”으로 평가됨