

상주영천고속도로 시설물 정밀점검 용역

외 관 조 사 망 도

가천교


2019.12

(주)명성엔지니어링



상주·영천방향

손 상 물 량 표

상주방향




영천방향





번호	손상내용	손상현황						비 고
		폭 (mm)	길이 (m)	너비 (m)	물량	단위	개소	
1	균열	0.3	5.0		5.00	m	1	신규
2	망상균열		5.0	2.0	10.0	m ²	1	신규
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17					</			

손 상 물 량 표

상주방향



영천방향



① 후타재균열
0.1/0.3X9EA


P2

P3



번호	손상내용	손상현황						비 고
		폭 (mm)	길이 (m)	너비 (m)	물량	단위	개소	
1	후타재균열	0.1	0.3		2.70	m	9	신규
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								

손 상 물 량 표

상주방향



영천방향




P3

P4



번호	손상내용	손상현황						비 고
		폭 (mm)	길이 (m)	너비 (m)	물량	단위	개소	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								

손 상 물 량 표

상주방향



영천방향




P6

P7



번호	손상내용	손상현황						비 고
		폭 (mm)	길이 (m)	너비 (m)	물량	단위	개소	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18				</				

손 상 물 량 표

상주방향



영천방향



P7

P8

번호	손상내용	손상현황						비 고
		폭 (mm)	길이 (m)	너비 (m)	물량	단위	개소	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								

