
1 위치도

2 외관조사

[STA.3+670~3+990[오 창]절 토 사 면]

오창절토05



← 오창방향 (시점)

(종점) 옥산방향 →

전경



1소단배수로 전경



점검계단 전경



낙석방지 울타리 전경



하부 전경



암반강도 작업사진



사면 경사 작업사진

□ 손상현황



현황	균열(0.5mm / 2.5m)
위치	STA.3+750 4소단배수로



현황	균열(1.0mm / 2.5m)
위치	STA.3+780 4소단배수로



현황	균열(1.3mm / 2.5m)
위치	STA.3+780 4소단배수로



현황	균열(0.5mm / 2.5m)
위치	STA.3+790 4소단배수로



현황	균열(0.5mm / 2.5m)
위치	STA.3+810 4소단배수로



현황	균열(0.6mm / 2.5m)
위치	STA.3+830 4소단배수로

□ 손상현황



현황	균열(0.3mm / 2.5m)
위치	STA.3+840 4소단배수로



현황	균열(0.4mm / 2.5m)
위치	STA.3+850 4소단배수로



현황	균열(0.8mm / 2.5m)
위치	STA.3+860 4소단배수로



현황	균열(0.3mm / 2.5m)
위치	STA.3+870 4소단배수로

현황	-
위치	-

현황	-
위치	-