
1 위치도

2 외관조사

[STA.4+650~4+930(옥 산)절 토 사면]

옥산절토04



← 옥산방향 (시점)

(종점) 오창방향 →

전경



1소단배수로 전경



낙석방지울타리 전경



야생동물 유도 울타리 전경



하부 전경



암반강도 작업사진



사면 경사 작업사진

□ 손상현황



현황	이완암
위치	STA.4+750~4+890 1~4단

현황	이완암
위치	STA.4+750~4+890 1~4단



현황	이완암
위치	STA.4+860~4+880 5단

현황	이완암
위치	STA.4+860~4+880 5단

--	--

--	--

현황	-
위치	-

현황	-
위치	-