
1 위치도

2 외관조사

[STA.4+600~4+920[오 창]절 토 사 면]

오창절토06



← 오창방향 (시점)

(종점) 옥산방향 →

전경



1소단배수로 전경



산마루측구 전경



낙석방지 울타리 전경



하부 전경



암반강도 작업사진



사면 경사 작업사진

□ 손상현황



현황	재균열(0.5mm / 2.5m)
위치	STA.4+780 4소단배수로

현황	재균열(1.0mm / 2.5m)
위치	STA.4+800 4소단배수로



현황	세굴 - 현재식생양호(A= 5.0m x 5.0m)
위치	STA.4+700 1단

현황	세굴 - 현재식생양호(A= 5.0m x 5.0m)
위치	STA.4+700 1단



현황	이완암
위치	STA.4+780~4+860 1~2단

현황	이완암
위치	STA.4+780~4+860 1~2단