
1 위치도

대상 시설물 위치도



2 외관조사

[STA.8+010~8+610(오 창)절 토 사 면]

오창절토11



← 부산방향 (시점)

(종점) 대구방향 →

전경



1소단배수로 전경



산마루측구 전경



점검사다리 전경



하부 전경



암반강도 작업사진



사면 경사 작업사진

□ 손상현황



현황	균열(1.0mm / 3.0m)
위치	STA.8+310~8+330 3소단배수로



현황	균열(1.0mm / 6.0m)
위치	STA.8+350 3소단배수로



현황	균열(1.0mm / 3.0m)
위치	STA.8+370~8+440 3소단배수로



현황	망상균열(A= 6.0m x 3.0m)
위치	STA.8+470 3소단배수로



현황	파손(A= 0.1m x 2.5m)
위치	STA.8+480 3소단배수로



현황	균열(1.0mm / 3.0m)
위치	STA.8+570 3소단배수로