
1 위치도

대상 시설물 위치도



2 외관조사

[STA.8+630~8+820[오 창]절 토 사 면]

오창절토12



← 오창방향 (시점)

(종점) 옥산방향 →

전경



1소단배수로 전경



산마루측구 전경



용벽 구간 전경



하부 전경



암반강도 작업사진



사면 경사 작업사진

□ 손상현황



현황 시공불량(A= 0.5m x 1.0m)

위치 STA.8+660 4소단배수로



현황 시공불량(A= 0.5m x 1.0m)

위치 STA.8+670 4소단배수로



현황 균열(1.5mm / 3.0m)

위치 STA.8+655 4소단배수로



현황 시공불량(A= 0.5m x 10.0m)

위치 STA.8+700 4소단배수로



현황 균열(2.0mm / 3.0m)

위치 STA.8+680 4소단배수로



현황 세굴(A= 1.0m x 5.0m)

위치 STA.8+780 3단