
1 위치도

2 외관조사

[서오창IC R-C STA.0+130~0+310(우안)절토사면]

서오창절토02	
	
← 요금소방향 (시점)	(종점) 옥산방향 →
전경	
	
1소단배수로 전경	산마루측구 및 점검계단 전경
	
야생동물 유도 울타리 전경	하부 전경
	
암반강도 작업사진	사면 경사 작업사진

□ 손상현황



현황	균열(0.3mm / 3.0m)
위치	STA.0+670 4소단배수로



현황	균열(0.3mm / 3.0m)
위치	STA.0+670 4소단배수로



현황	균열(0.3mm / 4.0m)
위치	STA.0+560 4소단배수로



현황	균열(2.0mm / 1.5m)
위치	STA.0+730 산마루측구



현황	균열(0.3mm / 7.5m)
위치	STA.0+700 4소단배수로



현황	균열(0.3mm / 7.5m)
위치	STA.0+700 4소단배수로

□ 손상현황



현황	균열(0.3mm / 4.0m)
위치	STA.0+495 4소단배수로

현황	균열(0.3mm / 4.0m)
위치	STA.0+495 4소단배수로



현황	균열(0.3mm / 1.5m)
위치	STA.0+730 산마루측구

현황	균열(0.3mm / 4.0m)
위치	STA.0+520 4소단배수로



현황	균열(0.5mm / 1.5m)
위치	STA.0+720 4소단배수로

현황	세굴(A= 1.0m x 10.0m)
위치	STA.0+760 1~2단