

안터교

바닥판하면 손상현황



안터교 바닥판하면 S1 종방향균열 0.2/3.0



안터교 바닥판하면 S1 측면 재료분리 1.0*0.2



안터교 바닥판하면 S1 콘크리트 파손 0.1*0.2



안터교 바닥판하면 S1-A1 횡방향균열 0.2/0.3



안터교 바닥판하면 S1-A2 박리 0.5*0.3



안터교 바닥판하면 S1-A2 박리 1.0*1.0

거더 및 가로보 손상현황



안터교 거더 S1-G1 A1측 인양홀 파손 0.2*0.2



안터교 거더 S1-G1 인양홀 파손 0.2*0.2 우



안터교 거더 S1-G2 인양홀 파손 0.2*0.2 우



안터교 거더 S1-G4 A1측 인양홀 파손 0.2*0.2



안터교 거더 S1-G4 인양홀 파손 0.2*0.2 좌



안터교 거더 S1-G7 인양홀 파손 0.2*0.2 좌

교대 손상현황



안터교 교대 A1 균열 0.2/1.0_신규



안터교 교대 A1 누수흔적 4.0*1.0_신규



안터교 교대 A1 박리 0.3*1.5_신규



안터교 교대 A1 박리 0.5*1.5_신규



안터교 교대 A1 파손 0.3*0.3_신규



안터교 교대 A2 박리 0.3*0.3 -신규-

교대 손상현황

	
안터교 교대 A2 박리 0.5*0.1 -신규-	안터교 교대 A2 박리 0.5*1.0 -신규-
	
안터교 교대 A2 박리 0.5*1.0 -신규-	

교량받침 손상현황

	
안터교 교량받침 A1-SH3 무수축물탈 균열 0.2/0.3_신규	

난간 및 연석 손상현황



안터교 이천방향 방호벽 S1 열화 30.0*0.5*2

	
안터교 이천방향 방호벽 S1 열화 30.0*0.5*2	