




ID:	덕이- 호수 #02
-----	------------

ID:	덕이- 호수 #02
-----	------------

Figure 1: Schematic diagram of the experimental setup. The diagram shows a rectangular arena with a central black square. Four numbered points are marked: ① (top-left), ② (top-right), ③ (bottom-left), and ④ (bottom-right). Dimensions are given: 0.1 x 2.0 for the distance from the center to the top edge, 0.5 x 3.5 for the distance from the center to the right edge, and 0.2 x 2.2 for the distance from the center to the bottom edge. A scale bar at the bottom indicates 0.5m.

③ $\frac{1}{2}$

⑤ 0

--	--

수

0.3X1.5

백태

50

9 아스콘 균열 0.5/1.0
 10 아스콘 0.5/0.5
 11 아스콘균열 0.5/1.5
 12 아스콘균열 0.5/0.6, 2ea


⑩ 아스콘 균열
0.5/0.5

② 아스콘균열
0.5/0.6, 2ea

손상물량표

[illegible]

KEY PLAN



和 記

72

 펀칭, 공동

	누수, 습윤부
	철근 콘크리트

	철근노출
	감제부식

망상균열

	박리, 파손
---	--------

	목재
	철재

	심 아
	좌 굴 변 형

재료분리

재료분리	용역명
---	------------


시공이음분리, 2025년도 경기북부 시중구조물
2종시설물 정밀안전점검 용역

☐	중부리	
☐	발주처	

☐	퇴직률	한국전력공사 경기북부분부
--------------------------	-----	---------------

 배수구	용역사 (주)명성엔지니어링
---	-------------------

 신축이음 본체	도면 번호	2
---	-------	---



ID: 덕이- 호수 #05

ID: 덕이- 호수 #05

			① 서다리미설치 1EA 
			

상부슬래브

바닥부

상부슬래브

바닥부

KEY PLAN

법
례

178

편집, 공동

 누수, 습윤부

 철근노출

☒ 감제부식

망상균열

 박리, 파손

	복 태
--	-----

	첨 하

	좌굴 변형
--	-------

손상물량표

[illegible]

용역명	2025년도 경기북부 지중구조물 ·2중시설물 정밀안전점검 용역
-----	---------------------------------------

발주처	한국전력공사 경기북부분부
용역사	(주)명성엔지니어링

도 면 번 호	5
---------	---

5

