


4. 향산2교 RAMP-A교

전경



교면포장 전경



신축이음장치 전경



바닥판하면 전경



거더 전경



교대 전경



교각 전경

손상현황

			
01 (25년 하반기)	바닥판 하면(S5) 상태양호	01 (26년 상반기)	바닥판 하면(S5) 상태양호
			
02 (25년 하반기)	교대(A1) 상태양호	02 (26년 상반기)	교대(A1) 상태양호
			
03 (25년 하반기)	교량받침(P5) 상태양호	03 (26년 상반기)	교량받침(P5) 상태양호

			
04 (25년 하반기)	거더(S5) 상태양호	04 (26년 상반기)	거더(S5) 상태양호
			
05 (25년 하반기)	교각(P5) 상태양호	05 (26년 상반기)	교각(P5) 상태양호
			
06 (25년 하반기)	신축이음(P2) 상태양호	06 (26년 상반기)	신축이음(P2) 상태양호

			
07 (25년 하반기)	교면포장(S1) 상태양호	07 (26년 상반기)	교면포장(S1) 상태양호
			
08 (25년 하반기)	배수구(S1) 막힘	08 (26년 상반기)	배수구(S1) 막힘 -보수-
			
09 (25년 하반기)	배수구(S1) 막힘	09 (26년 상반기)	배수구(S1) 막힘 -보수-

			
10 (25년 하반기)	배수구(S1) 막힘	10 (26년 상반기)	배수구(S1) 막힘 -보수-
			
11 (25년 하반기)	방호벽(S2) 균열(0.3mm이상)	11 (26년 상반기)	방호벽(S2) 균열(0.3mm이상)
			
12 (25년 하반기)	점검사다리(P4) 상태양호	12 (26년 상반기)	점검사다리(P4) 상태양호

			
13 (26년 상반기)	신축이음(A1) 유간 토사퇴적	13 (26년 상반기)	신축이음(A25)
			
14 (26년 상반기)	거더(S3-G1) 좌측 파손	14 (26년 상반기)	거더(S25-G1)