

5. 향산2교 RAMP-B교

전경



교면포장 전경



신축이음장치 전경




바닥판하면 전경



거더 전경




교대 전경






교각 전경


손상현황

			
01 (25년 하반기)	바닥판 하면(S5) 망상균열(cw=0.2mm)	01 (26년 상반기)	바닥판 하면(S5) 망상균열(cw=0.2mm)
			
02 (25년 하반기)	거더(S5-G3-LW) 망상균열(cw=0.2mm)	02 (26년 상반기)	거더(S5-G3-LW) 망상균열(cw=0.2mm)
			
03 (25년 하반기)	가로보(S5) 상태양호	03 (26년 상반기)	가로보(S5) 상태양호

			
04 (25년 하반기)	교대(A1) 상태양호	04 (26년 상반기)	교대(A1) 상태양호
			
05 (25년 하반기)	교각(P1) 상태양호	05 (26년 상반기)	교각(P1) 상태양호
			
06 (25년 하반기)	교량받침(P5) 본체 부식	06 (26년 상반기)	교량받침(P5) 본체 부식

	
07 (25년 하반기)	07 (26년 상반기)
신축이음(A1) 유간 토사퇴적	신축이음(A1) 유간 토사퇴적
	
08 (25년 하반기)	08 (26년 상반기)
신축이음(P2) 후타재 균열	신축이음(P2) 후타재 균열
	
09 (25년 하반기)	09 (26년 상반기)
신축이음(P5) 유간 토사퇴적	신축이음(P5) 유간 토사퇴적

			
10 (25년 하반기)	교면포장(S2) 망상균열	10 (26년 상반기)	교면포장(S2) 망상균열
			
11 (25년 하반기)	배수구(S1) 막힘	11 (26년 상반기)	배수구(S1) 막힘
			
12 (25년 하반기)	배수구(S6) 막힘	12 (26년 상반기)	배수구(S6) 막힘

			
13 (25년 하반기)	방호벽(S1) 균열(0.3mm이상)	13 (26년 상반기)	방호벽(S1) 균열(0.3mm이상)
			
14 (25년 하반기)	방호벽(S1) 델리네이터 파손	14 (26년 상반기)	방호벽(S1) 델리네이터 파손
			
15 (25년 하반기)	점검시설(P5) 점검사다리 상태양호	15 (26년 상반기)	점검시설(P2) 점검사다리 상태양호

	
16 (25년 하반기)	16 (26년 상반기)
	
17 (25년 하반기)	17 (26년 상반기)
	
18 (25년 하반기)	18 (26년 상반기)
점검시설(P5) 점검로 상태양호	점검시설(P5) 점검로 상태양호
신축이음(P7) 덮개 볼트탈락(4ea)	신축이음(P7) 덮개 볼트탈락(4ea)
방호벽(S3) 균열(0.3mm미만)	방호벽(S3) 균열(0.3mm미만)