

8. 군하교

전경



교면포장 전경



신축이음장치 전경



바닥판하면 전경



교명주 전경



교대 전경




교각 전경

손상현황

			
01 (25년 하반기)	바닥판하면(S1) 균열(0.3mm미만)	01 (26년 상반기)	바닥판하면(S1) 균열(0.3mm미만)
			
02 (25년 하반기)	바닥판하면(S1) 보수부 백태	02 (26년 상반기)	바닥판하면(S1) 보수부 백태
			
03 (25년 하반기)	바닥판하면(S5) 녹물 및 백태	03 (26년 상반기)	바닥판하면(S5) 녹물 및 백태

			
04 (25년 하반기)	배수관(S6) 주변 박락	04 (26년 상반기)	배수관(S6) 주변 박락
			
05 (25년 하반기)	배수관(S6) 주변 백태	05 (26년 상반기)	배수관(S6) 주변 백태
			
06 (25년 하반기)	교대(A2) 벽체 전면 보수부 균열(0.3mm미만)	06 (26년 상반기)	교대(A2) 벽체 전면 보수부 균열(0.3mm미만)

			
07 (25년 하반기)	교각(P4) 일부 침식-토포 확보	07 (26년 상반기)	교각(P4) 일부 침식-토포 확보
			
08 (25년 하반기)	교면포장(A2) 서울방향 접속부 포장 파손	08 (26년 상반기)	교면포장(A2) 서울방향 접속부 포장 파손
			
09 (25년 하반기)	교면포장(S2) 강화방향 패임	09 (26년 상반기)	교면포장(S2) 강화방향 패임

	
10 (25년 하반기)	10 (26년 상반기)
	
11 (25년 하반기)	11 (26년 상반기)
	
12 (25년 하반기)	12 (26년 상반기)

신축이음(A1) 표면열화

신축이음(A1) 표면열화

신축이음(A1) 차수판 미설치

신축이음(A1) 차수판 미설치

신축이음(A2)
토사퇴적, 균열, 파손

신축이음(A2)
토사퇴적, 균열, 파손

	
13 (25년 하반기)	13 (26년 상반기)
	
14 (25년 하반기)	14 (26년 상반기)
	
15 (25년 하반기)	15 (26년 상반기)
신축이음(A2) 고무재 탈락	신축이음(A2) 고무재 탈락
배수시설(S2) 배수관 파손	배수시설(S2) 배수관 파손
배수시설(S5) 배수관 탈락	배수시설(S5) 배수관 탈락

			
16 (25년 하반기)	교명관(S1) 탈락	16 (26년 상반기)	교명관(S1) 탈락
			
17 (25년 하반기)	중양분리대(S1) 균열(0.3mm이상)	17 (26년 상반기)	중양분리대(S1) 균열(0.3mm이상)
			
18 (25년 하반기)	옹벽 (A2) 우측 보수부 균열(0.3mm미만)	18 (26년 상반기)	옹벽 (A2) 우측 보수부 균열(0.3mm미만)

	
19 (25년 하반기)	19 (26년 상반기)
	
20 (25년 하반기)	20 (26년 상반기)
	
21 (25년 하반기)	21 (26년 상반기)

22 (25년 하반기)	22 (26년 상반기)
23 (25년 하반기)	23 (26년 상반기)
24 (25년 하반기)	24 (26년 상반기)
교면포장(S1~S2) 강화방향 소성변형	교면포장(S1~S2) 강화방향 소성변형

	
25 (25년 하반기)	25 (26년 상반기)
	
26 (26년 상반기)	27 (26년 상반기)
교각(P1) 균열 (0.3mm미만)	교각(P1) 균열 (0.3mm미만)
	
배수시설(S1) 배수관 파손	교명판(A2) 탈락