

10. 마송IC교

전경



교면포장 전경



신축이음장치 전경




바닥판하면 전경



거더 전경






교대 전경






교대 전경

손상현황

			
01 (25년 하반기)	거더(A1G1, 마송) 파손	01 (26년 상반기)	거더(A1G1, 마송) 파손
			
02 (25년 하반기)	거더(A1G1, 마송) 파손	02 (26년 상반기)	거더(A1G1, 마송) 파손
			
03 (25년 하반기)	교량받침(A1-Sh5, 마송) 플레이트 부식	03 (26년 상반기)	교량받침(A1-Sh5, 마송) 플레이트 부식






	
04 (25년 하반기)	교대(A1, 마송) 날개벽 표면오염
	
05 (25년 하반기)	교대(A1, 마송) 벽체 박리
	
06 (25년 하반기)	거더(A1G2, 누산) 박락
	06 (26년 상반기)
	거더(A1G2, 누산) 박락


			
07 (25년 하반기)	거더(A2G1, 마송) 파손	07 (26년 상반기)	거더(A2G1, 마송) 파손
			
08 (25년 하반기)	바닥판 하면(S1, 누산) 균열(0.3mm미만)	08 (26년 상반기)	바닥판 하면(S1, 누산) 균열(0.3mm미만)
			
09 (25년 하반기)	바닥판 하면(S1, 접속부) 실란트 열화	09 (26년 상반기)	바닥판 하면(S1, 접속부) 실란트 열화

	
10 (25년 하반기)	10 (26년 상반기)
	
11 (25년 하반기)	11 (26년 상반기)
	
12 (25년 하반기)	12 (26년 상반기)
교량받침 (A2-Sh5, 마송) 플레이트 부식	교량받침 (A2-Sh5, 마송) 플레이트 부식
교대(A1, 누산) 흥벽 균열(0.3mm미만)	교대(A1, 누산) 흥벽 균열(0.3mm미만)
교대(A1, 누산) 벽체 균열(0.3mm미만)	교대(A1, 누산) 벽체 균열(0.3mm미만)

	
13 (25년 하반기)	교대(A1, 누산) 교좌면 토사퇴적
	
14 (25년 하반기)	교대(A2, 마송) 벽체 박리
	
15 (25년 하반기)	교대(A2, 접속부) 벽체 실란트 열화

			
16 (25년 하반기)	교면포장(S1, 누산) 마모	16 (26년 상반기)	교면포장(S1, 누산) 마모
			
17 (25년 하반기)	신축이음(A1, 누산) 본체 부식	17 (26년 상반기)	신축이음(A1, 누산) 본체 부식
			
18 (25년 하반기)	신축이음(A2, 누산) 본체 부식	18 (26년 상반기)	신축이음(A2, 누산) 본체 부식

	
19 (25년 하반기)	19 (26년 상반기)
배수시설(S1, 마송) 누수	배수시설(S1, 마송) 누수
	
20 (25년 하반기)	20 (26년 상반기)
배수시설(S1, 마송) 배수관 탈락	배수시설(S1, 마송) 배수관 탈락
	
21 (25년 하반기)	21 (26년 상반기)
교면포장(S1, 마송) 망상균열	교면포장(S1, 마송) 망상균열

	
22 (25년 하반기)	22 (26년 상반기)
교면포장(S1, 마송) 아스콘 균열	교면포장(S1, 마송) 아스콘 균열
	
23 (25년 하반기)	23 (26년 상반기)
교면포장(S1, 마송) 망상균열	교면포장(S1, 마송) 망상균열
	
24 (25년 상반기)	24 (26년 상반기)
신축이음(A1, 마송) 본체 부식	신축이음(A1, 마송) 본체 부식

25 (25년 하반기)	신축이음(A2, 마송) 후타재 균열	25 (26년 상반기)	신축이음(A2, 마송) 후타재 균열
26 (25년 하반기)	가로보 상태양호	26 (26년 상반기)	가로보 상태양호
27 (25년 상반기)	배수시설(S1, 마송) 배수구 막힘 보수완료	27 (26년 상반기)	배수시설(S1, 마송) 배수구 막힘 보수완료

			
28 (25년 하반기)	배수시설(S1, 마송) 배수구 이물질 퇴적 보수완료	28 (26년 상반기)	배수시설(S1, 마송) 배수구 이물질 퇴적 보수완료
			
29 (25년 하반기)	배수시설(S1, 누산) 배수구 막힘 보수	29 (26년 상반기)	배수시설(S1, 누산) 배수구 막힘 보수 상태양호
			
30 (25년 상반기)	방호울타리(S1, 마송) 균열(0.3mm미만)	30 (26년 상반기)	방호울타리(S1, 마송) 균열(0.3mm미만)



31
(25년 하반기)

배수시설(S1, 누산)
배수관 누수



31
(26년 상반기)

배수시설(S1, 누산)
배수관 누수



32
(25년 하반기)

신축이음(A2, 누산)
후타재 균열(0.3mm미만)




32
(26년 상반기)

신축이음(A2, 누산)
후타재 균열(0.3mm미만)



33
(25년 상반기)

방음벽(S1, 누산)
방음벽 유리 파손



33
(26년 상반기)

방음벽(S1, 누산)
방음벽 유리 파손

			
34 (25년 하반기)	신축이음 (A1, 누산) 후타재 균열 (0.3mm미만)	34 (26년 상반기)	신축이음 (A1, 누산) 후타재 균열 (0.3mm미만)
			
35 (25년 하반기)	중양분리대 (누산) 균열부백태 (0.3mm미만)	35 (26년 상반기)	중양분리대 (누산) 균열부백태 (0.3mm미만)

