


17. 태리IC육교(상)

전경



교면포장 전경



신축이음장치 전경



바닥판하면 전경



거더외부 전경




교대 전경





교량받침 전경

손상현황

	
01 (25년 하반기)	01 (26년 상반기)
	
02 (25년 하반기)	02 (26년 상반기)
	
03 (25년 하반기)	03 (26년 상반기)
받침 (A2-Sh3) 부식	받침 (A2-Sh3) 부식


			
04 (25년 하반기)	받침 (A1-Sh2) 물탈 파손	04 (26년 상반기)	받침 (A1-Sh2) 물탈 파손
			
05 (25년 하반기)	교대 (A1) 균열 (0.5mm이상)	05 (26년 상반기)	교대 (A1) 균열 (0.5mm이상)
			
06 (25년 하반기)	교대 (A1) 잡철물 노출	06 (26년 상반기)	교대 (A1) 잡철물 노출

	
07 (25년 하반기)	07 (26년 상반기)
	
08 (25년 하반기)	08 (26년 상반기)
	
09 (25년 하반기)	09 (26년 상반기)
	

			
10 (25년 하반기)	교대(A2) 누수흔적	10 (26년 상반기)	교대(A2) 누수흔적
			
11 (25년 하반기)	교대(A2) 망상균열	11 (26년 상반기)	교대(A2) 망상균열
			
12 (25년 하반기)	교대(A2) 날개벽 파손/경미	12 (26년 상반기)	교대(A2) 날개벽 파손/경미

	
13 (25년 하반기)	13 (26년 상반기)
교대(A2) 법면 상부 몰탈 파손	교대(A2) 법면 상부 몰탈 파손
	
14 (25년 하반기)	14 (26년 상반기)
교대(A2) 법면 이격(30mm)	교대(A2) 법면 이격(30mm)
	
15 (25년 하반기)	15 (26년 상반기)
신축이음(A1) 유간 토사퇴적	신축이음(A1) 유간 토사퇴적

			
16 (25년 하반기)	차수관(A2) 볼트 탈락	16 (26년 상반기)	차수관(A2) 볼트 탈락
			
17 (25년 하반기)	신축이음(A2) 후타재 파손	17 (26년 상반기)	신축이음(A2) 후타재 파손
			
18 (25년 하반기)	배수구 막힘	18 (26년 상반기)	배수구 막힘

	
19 (25년 하반기)	19 (26년 상반기)
	
20 (25년 하반기)	20 (26년 상반기)
	
21 (26년 상반기)	22 (26년 상반기)

방호벽 균열(0.3mm미만)

방호벽 균열(0.3mm미만)

중분대(S1) 실란트 파손

중분대(S1) 실란트 파손

교대(A1) 균열(0.5mm이상)

교대(A1) 균열(0.5mm이상)