

28. 옥림2교

전경



교면포장 전경



신축이음장치 전경



바닥판하면 전경



거더 전경



교대 전경



교량받침 전경

손상현황

			
01 (25년 하반기)	바닥판하면 누수, 박리, 박락	01 (26년 상반기)	바닥판하면 누수, 박리, 박락
			
02 (25년 하반기)	바닥판하면 철근노출	02 (26년 상반기)	바닥판하면 철근노출
			
03 (25년 하반기)	거더 균열부 백태(0.3mm미만)	03 (26년 상반기)	거더 균열부 백태(0.3mm미만)

			
04 (25년 하반기)	교대 법면 블록 유실	04 (26년 상반기)	교대 법면 블록 유실
			
05 (25년 하반기)	교대 법면 블록 유실	05 (26년 상반기)	교대 법면 블록 유실
			
06 (25년 하반기)	교대 홍벽 재료분리	06 (26년 상반기)	교대 홍벽 재료분리

			
07 (25년 하반기)	교대 균열(0.3mm미만)	07 (26년 상반기)	교대 균열(0.3mm미만)
			
08 (25년 하반기)	교대 균열(0.3mm미만)	08 (26년 상반기)	교대 균열(0.3mm미만)
			
09 (25년 하반기)	교대 실란트 파손	09 (26년 상반기)	교대 실란트 파손

			
10 (25년 하반기)	교대 박락	10 (26년 상반기)	교대 박락
			
11 (26년 상반기)	교대 박락	12 (26년 상반기)	교면포장 포장 균열
			
13 (26년 상반기)	교면포장 포장 균열/망상균열	14 (26년 상반기)	교면포장 포장 마모

	
15 (25년 하반기)	15 (26년 상반기)
교면포장 포트홀	교면포장 포트홀
	
16 (25년 하반기)	16 (26년 상반기)
신축이음 유간 토사퇴적	신축이음 유간 토사퇴적
	
17 (25년 하반기)	17 (26년 상반기)
배수시설 배수구 막힘	배수시설 배수구 막힘 보수