

30. 용정교

전경



교면포장 전경



신축이음장치 전경



바닥판하면 전경



거더 전경



교대 전경




교량받침 전경



손상현황

			
01 (25년 하반기)	바닥판하면 균열부 백태(0.3mm미만)	01 (26년 상반기)	바닥판하면 균열부 백태(0.3mm미만)
			
02 (25년 하반기)	바닥판하면 층분리	02 (26년 상반기)	바닥판하면 층분리
			
03 (25년 하반기)	교대 균열(0.3mm미만)	03 (26년 상반기)	교대 균열(0.3mm미만)

			
04 (25년 하반기)	교대 균열(0.3mm미만)	04 (26년 상반기)	교대 균열(0.3mm미만)
			
05 (25년 하반기)	교대 균열(0.3mm미만)	05 (26년 상반기)	교대 균열(0.3mm미만)
			
06 (25년 하반기)	교대 망상균열(0.3mm미만)	06 (26년 상반기)	교대 망상균열(0.3mm미만)

	
07 (25년 하반기)	07 (26년 상반기)
	
08 (25년 하반기)	08 (26년 상반기)
	
09 (25년 하반기)	09 (26년 상반기)

	
10 (25년 하반기)	10 (26년 상반기)
교면포장 포장 균열	교면포장 포장 망상균열
	
11 (25년 하반기)	11 (26년 상반기)
교면포장 포장 균열	신축이음 본체 부식
	
12 (25년 하반기)	12 (26년 상반기)
교면포장 포장 파손	교면포장 포장 파손

	
13 (26년 상반기)	14 (26년 상반기)
	
15 (25년 하반기)	15 (26년 상반기)
	
16 (25년 하반기)	16 (26년 상반기)

신축이음 후타재 균열(0.3mm미만)

신축이음 후타재 균열(0.3mm미만)

신축이음 유간 토사퇴적

신축이음 유간 토사퇴적

배수시설 배수구 막힘

배수시설 배수구 막힘 보수

			
17 (25년 하반기)	방호벽 균열(0.3mm미만)	17 (26년 상반기)	방호벽 균열(0.3mm미만)
			
18 (25년 하반기)	방호벽 균열(0.3mm미만)	18 (26년 상반기)	방호벽 균열(0.3mm미만)

