

34. 태리

전경



교면포장 전경



계단부 전경



배수시설 전경



바닥판하면 및 거더 전경




엘리베이터 전경




교각 전경

손상현황

			
01 (25년 하반기)	거더외부 굽힘	01 (26년 상반기)	거더외부 굽힘
			
02 (25년 하반기)	바닥판 상태양호	02 (26년 상반기)	바닥판 상태양호
			
03 (25년 하반기)	가동단 상태양호	03 (26년 상반기)	가동단 상태양호

	
04 (25년 하반기)	04 (26년 상반기)
	
05 (25년 하반기)	05 (26년 상반기)
	
06 (25년 하반기)	06 (26년 상반기)
상부 포장 상태양호	상부 포장 상태양호

			
07 (25년 하반기)	배수구 양호	07 (26년 상반기)	배수구 양호
			
08 (25년 하반기)	배수구 양호	08 (26년 상반기)	배수구 양호
			
09 (25년 하반기)	낙하물방지망 미설치	09 (26년 상반기)	낙하물방지망 미설치

			
10 (25년 하반기)	계단(김포) 부식	10 (26년 상반기)	계단(김포) 부식
			
11 (25년 하반기)	계단(김포) 도장박락	11 (26년 상반기)	계단(김포) 도장박락
			
12 (25년 하반기)	바닥판 계단 연결부 누수	12 (26년 상반기)	바닥판 계단 연결부 누수

