

## 2. 비 봉 교



## 전경



측면 전경(매송방향)



측면 전경(비봉방향)



교면포장 전경



바닥판하면 전경



교대 전경




하부 전경

# 손상현황



01  
(25년 상반기)

교대(A1) 날개벽 백태



01  
(26년 상반기)

교대(A1) 날개벽 백태



02  
(25년 상반기)

교대(A1) 날개벽 웅벽 파손



02  
(26년 상반기)

교대(A1) 날개벽 웅벽 파손



03  
(25년 상반기)

교대(A2) 균열(0.3mm미만)



03  
(26년 상반기)

교대(A2) 균열(0.3mm미만)