

4. 양 노 4 교

전경



측면 전경



교면포장 전경



바닥판하면 전경



거더 전경



교대 전경



교량받침 전경

손상현황

			
01 (25년 상반기)	신축이음(A1) 하부 누수	01 (26년 상반기)	신축이음(A1) 하부 누수
			
02 (25년 상반기)	신축이음(A1) 후타재 균열	02 (26년 상반기)	신축이음(A1) 후타재 균열
			
03 (25년 상반기)	교대(A1) 마감불량	03 (26년 상반기)	교대(A1) 마감불량

	
04 (25년 상반기)	교대(A2) 백태
	
05 (26년 상반기)	신축이음(A2) 하부 누수
	
07 (26년 상반기)	교대(A2) 백태
08 (26년 상반기)	교대(A2) 백태

