

5. 개 무 교

전경



측면 전경(매송방향)



난간 및 연석 전경



교면포장 전경



바닥판하면 전경






교대 전경



하부 전경

손상현황

	
01 (25년 상반기)	01 (26년 상반기)
	
02 (25년 상반기)	02 (26년 상반기)
	
03 (25년 상반기)	03 (26년 상반기)
	
바닥판하면(S1) 보수부 재균열	바닥판하면(S1) 보수부 재균열

			
04 (25년 상반기)	교대(A1) 파손	04 (26년 상반기)	교대(A1) 파손
			
05 (25년 상반기)	교대(A1) 누수흔적	05 (26년 상반기)	교대(A1) 누수흔적
			
06 (25년 상반기)	교대(A2) 누수흔적	06 (26년 상반기)	교대(A2) 누수흔적

