

6. 내 리 교

전경



측면 전경



난간 및 연석 전경




교면포장 전경



바닥판하면 전경




교대 전경



하부 전경

손상현황

			
01 (25년 상반기)	난간 및 연석(S1) 중분대 균열(0.3mm이상)	01 (26년 상반기)	난간 및 연석(S1) 중분대 균열(0.3mm이상)
			
02 (25년 상반기)	바닥판하면(S1) 측면 균열	02 (26년 상반기)	바닥판하면(S1) 측면 균열
			
03 (25년 상반기)	바닥판하면(S1) 측면 박락	03 (26년 상반기)	바닥판하면(S1) 측면 박락

	
04 (25년 상반기)	04 (26년 상반기)
	
05 (25년 상반기)	05 (26년 상반기)
	
06 (25년 상반기)	06 (26년 상반기)
	

