


2. 샘 내 I C 1 교

전경



교면포장 전경



신축이음장치 전경



바닥판하면 전경



거더 전경



교대 전경





교각 전경

손상현황

			
01 (25년 하반기)	교면포장(S3) 포장 균열	01 (26년 상반기)	교면포장(S3) 포장 균열
			
02 (25년 하반기)	배수시설(S3) 배수구 막힘	02 (26년 상반기)	배수시설(S3) 배수구 막힘
			
03 (25년 하반기)	난간 및 연석(S1) 방호벽 보수부 재균열	03 (26년 상반기)	난간 및 연석(S1) 방호벽 보수부 재균열

	
04 (25년 하반기)	04 (26년 상반기)
	
05 (25년 하반기)	05 (26년 상반기)
	
06 (25년 하반기)	06 (26년 상반기)

	
07 (25년 하반기)	07 (26년 상반기)
신축이음(A1) 후타재 단차	신축이음(A1) 후타재 단차
	
08 (25년 하반기)	08 (26년 상반기)
신축이음(A2) 부식	신축이음(A2) 부식
	
09 (25년 하반기)	09 (26년 상반기)
신축이음(A2) 후타재 단차	신축이음(A2) 후타재 단차

	
10 (25년 하반기)	10 (26년 상반기)
	
11 (25년 하반기)	11 (26년 상반기)
	
12 (25년 하반기)	12 (26년 상반기)
교량받침(A1-SH2) 받침 고무 들뜸	교량받침(A1-SH2) 받침 고무 들뜸
교량받침(A2-SH2) 받침 플레이트 부식	교량받침(A2-SH2) 받침 플레이트 부식
교대(A1) 파손	교대(A1) 파손

			
13 (25년 하반기)	교대(A1) 표면오염	13 (26년 상반기)	교대(A1) 표면오염
			
14 (25년 하반기)	교대(A2) 망상균열(0.3mm미만)	14 (26년 상반기)	교대(A2) 망상균열(0.3mm미만)
			
15 (25년 하반기)	교각(P1) 균열(0.3mm미만)	15 (26년 상반기)	교각(P1) 균열(0.3mm미만)