


4. 천 천 I C 1 교

전경



교면포장 전경



신축이음장치 전경




바닥판하면 전경



거더 전경




교대 전경







교각 전경

손상현황

			
01 (25년 하반기)	교면포장(S2) 매송방향 포장 균열	01 (26년 상반기)	교면포장(S2) 매송방향 포장 균열
			
02 (25년 하반기)	배수시설(S2) 매송방향 배수구 막힘	02 (26년 상반기)	배수시설(S2) 매송방향 배수구 막힘
			
03 (25년 하반기)	난간 및 연석(S1) 매송방향 박리	03 (26년 상반기)	난간 및 연석(S1) 매송방향 박리

	
04 (25년 하반기)	04 (26년 상반기)
	
05 (25년 하반기)	05 (26년 상반기)
	
06 (25년 하반기)	06 (26년 상반기)

	
07 (25년 하반기)	07 (26년 상반기)
신축이음(A1) 비봉방향 후타재 파손	신축이음(A1) 비봉방향 후타재 파손
	
08 (25년 하반기)	08 (26년 상반기)
교량받침(A1-SH1) 받침 고무재 갈라짐	교량받침(A1-SH1) 받침 고무재 갈라짐
	
09 (25년 하반기)	09 (26년 상반기)
교량받침(A1-SH2) 받침 고무 들뜸	교량받침(A1-SH2) 받침 고무 들뜸

	
10 (25년 하반기) 교량받침 (A2-SH1) 받침 플레이트 부식	10 (26년 상반기) 교량받침 (A2-SH1) 받침 플레이트 부식
	
11 (25년 하반기) 교량받침 (P1-SH1) 받침 고무재 갈라짐	11 (26년 상반기) 교량받침 (P1-SH1) 받침 고무재 갈라짐
	
12 (25년 하반기) 거더내부 (S3-G1) 폐기물 적치	12 (26년 상반기) 거더내부 (S3-G1) 폐기물 적치

			
13 (25년 하반기)	교대(A1) 균열(0.3mm미만)	13 (26년 상반기)	교대(A1) 균열(0.3mm미만)
			
14 (25년 하반기)	교대(A1) 표면오염	14 (26년 상반기)	교대(A1) 표면오염
			
15 (25년 하반기)	교각(A2) 보수부 재균열	15 (26년 상반기)	교각(A2) 보수부 재균열

			
16 (25년 하반기)	교각(P1) 균열(0.3mm미만)	16 (26년 상반기)	교각(P1) 균열(0.3mm미만)
			
17 (26년 상반기)	신축이음(A2) 신축이음 하부 누수	18 (26년 상반기)	신축이음(A1) 매송방향 후타재 단차
			
19 (26년 상반기)	신축이음(A2) 매송방향 후타재 단차	20 (26년 상반기)	교량받침(P2-SH2) 받침 고무재 갈라짐

