

6. 계단식옹벽 (STA.2+040~2+148)

전경



시점부 전경



중점부 전경



전면부 전경



옹벽 1단 상부 전경




기초, 지반부 전경



옹벽 배수시설 배수공 전경

손상현황

	
01 (25년 하반기)	01 (26년 상반기)
전면부(2+050) 균열(0.3mm이상)	전면부(2+050) 균열(0.3mm이상)
	
02 (25년 하반기)	02 (26년 상반기)
전면부(2+100) 신축이음부 열화	전면부(2+100) 신축이음부 열화
	
03 (25년 하반기)	03 (26년 상반기)
전면부(2+070) 수목 적치	전면부(2+070) 수목 적치

			
04 (25년 하반기)	기초부 상태현황	04 (26년 상반기)	기초부 상태현황
			
05 (25년 하반기)	배수시설 배수공 상태현황	05 (26년 상반기)	배수시설 배수공 상태현황
			
06 (26년 상반기)	전면부(2+055) 균열(0.3mm이상)	07 (26년 상반기)	전면부(2+065) 균열(0.3mm이상)

