



번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 탈락, 박리, 박락		돌짐, 충농리
	절근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누분, 습윤부		기타




번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		벽면, 굴루
	파손, 탈락, 박리, 박락		흙탕, 흙불리
	철근노출		부식
	채수		채수구멍합
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타




번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

손상범례			
구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 탈락, 박리, 박락		돌출, 총흔리
	절근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타





번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 탈락, 박리, 박락		돌짐, 충농리
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타




번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

손상범례			
구분	명칭	구분	명칭
	균열		백대, 결로
	파손, 탈락, 박리, 박락		돌종, 층분리
	철근노출		부식
	채수		배수구막형
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타




손상물량표

번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								



손상범례

구분	명칭	구분	명칭
	균열		박대, 결로
	파손, 탈락, 박리, 박락		틀림, 총분리
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타



번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		백래, 결로
	파손, 탈락, 박리, 박락		불응, 총분리
	절근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타

번호	위치	손상내용	손상물량					비고
			폭	깊이	개소	단위	수량	
1	교대	누수흔적	0.2	1.0	1	㎡	0.20	
2	교대	균열	0.2	0.8	1	m	0.80	
3	교대	파손 및 월근노출	12.0	0.1	1	㎡	1.20	손상변경
4	교대	누수흔적	0.2	1.0	1	㎡	0.20	
5	교대	누수흔적	1.0	4.0	1	㎡	4.00	
6	신축이음	흙응제 발락	-	2.0	1	m	2.00	
7	교대	누수흔적	5.0	2.0	1	㎡	10.00	
8	교대	누수흔적	7.0	2.0	1	㎡	14.00	
9	교대	균열	0.1	2.0	1	m	2.00	신규
10	교대	누수흔적	1.0	4.0	1	㎡	4.00	신규
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								




구름	영 칭	구름	영 칭
	건열		백담, 칠문
	파산, 탈락, 박진, 박락		충충, 충충진
	절근노출		부식
	제수		배수구멍형
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타

연호고가교

안심방향
A1
범몰방향

범몰방향
A2
안심방향

067



손상물량표

번	위치	손상내용	손상물량					비고
			목	길이	개소	단위	수량	
1	포장부	아스콘 균열	-	1.2	3	m	3.60	
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

손상범례

구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 틈새, 박리, 박락		돌조, 층분리
	철근노출		부식
	침하		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타

