



번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 탈락, 박리, 박락		들뜸, 총흔리
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타





번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		벽면, 천장
	파손, 탈락, 박리, 박락		틀림, 흔들림
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타





번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								



구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 탈락, 박리, 박락		돌짐, 충흔리
	절근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타



구분	명칭	구분	명칭
	균열		벽대, 절로
	파손, 밀라, 박리, 땀라		통풍, 통분리
	절근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타




번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								





향광매체

안심





번호	위치	손상내용	손상물량					비고
			폭	깊이	계소	단위	수량	
1	거터내부	점경등불량	-	-	1	EA	1.00	신규
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

손상범례			
구분	명칭	구분	명칭
	균열		백대, 결로
	파손, 탈락, 박리, 박락		들뜸, 층분리
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타



영역사	(주)명성엔지니어링	발주처	대구 동부순환도로 (주)	영역명	2024년 범안로 시설물 정기 및 정밀안전점검 기술용역	구간	연호고가교	위치	S1 교면포장	N O	034
-----	------------	-----	---------------	-----	--------------------------------	----	-------	----	---------	--------	-----





번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		백래, 결로
	파손, 탈락, 박리, 박락		불응, 총분리
	절근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타

번호	위치	손상내용	손상물량					비고
			폭	깊이	개소	단위	수량	
1	교대	누수흔적	0.2	1.0	1	㎡	0.20	
2	교대	균열	0.2	0.8	1	m	0.80	
3	교대	파손 및 월근노출	12.0	0.1	1	㎡	1.20	손상변경
4	교대	누수흔적	0.2	1.0	1	㎡	0.20	
5	교대	누수흔적	1.0	4.0	1	㎡	4.00	
6	신축이음	흙응제 발락	-	2.0	1	m	2.00	
7	교대	누수흔적	5.0	2.0	1	㎡	10.00	
8	교대	누수흔적	7.0	2.0	1	㎡	14.00	
9	교대	균열	0.1	2.0	1	m	2.00	신규
10	교대	누수흔적	1.0	4.0	1	㎡	4.00	신규
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								




구분	명칭	구분	명칭
	진열		배대, 질문
	파손, 탈락, 박진, 박락		충충, 충진기
	철근노출		부식
	제수		배수구막힘
	이물질 퇴적		변형
	양상균열		열화
	재료분리		보수
	누수, 습윤부		기타

연호고가교

안심방향
A1
범몰방향

범몰방향
A2
안심방향

067



손상물량표

번	위치	손상내용	손상물량					비고
			목	길이	개소	단위	수량	
1	포장부	아스콘 균열	-	1.2	3	m	3.60	
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

손상범례

구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 틈새, 박리, 박락		틀림, 총분리
	철근노출		부식
	침하		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타

