



번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 탈락, 박리, 박락		돌짐, 충농리
	절근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누분, 습윤부		기타





번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

손상범례			
구분	명칭	구분	명칭
	균열		백대, 결로
	파손, 탈락, 빠리, 박락		들뜸, 층분리
	철근노출		무식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타




번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1	거터내부	점경등불량	-	-	1	EA	1.00	신규
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	근철		벽대, 걸루
	파손, 탈락, 박리, 박락		돌층, 층돌리
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상근철		열화
	재료분리		보수
	누수, 습윤부		기타




손상물량표

번호	위치	손상내용	손상물량					비고
			목	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								




손상범례

구분	명칭	구분	명칭
	균열		박대, 결로
	파손, 탈락, 박리, 박락		틀림, 총분리
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타






번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		벽면, 천로
	파손, 탈락, 박리, 박락		틀림, 흔들림
	철근노출		부식
	채수		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타



번호	위치	손상내용	손상물량					비고
			폭	길이	개소	단위	수량	
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

구분	명칭	구분	명칭
	균열		백래, 결로
	파손, 탈락, 박리, 박락		불응, 총분리
	절근노출		부식
	채수		배수구멍침
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타



손상물량표

번	위치	손상내용	손상물량					비고
			목	길이	개소	단위	수량	
1	포장부	아스콘 균열	-	1.2	3	m	3.60	
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								

손상범례

구분	명칭	구분	명칭
	균열		백태, 결로
	파손, 틈새, 박리, 박락		틀림, 총분리
	철근노출		부식
	침하		배수구막힘
	이물질 퇴적		변형
	망상균열		열화
	재료분리		보수
	누수, 습윤부		기타

