

ID: 문발- 윤정 #6		손 상 물 량 표							
번호	신(N) 구(P)	손상내용	손상규모			개소	수량	단위	비고
			폭 (mm)	너비 (m)	깊이 (m)				
1	구	관입(0.3mm이전)	0.28		1.50	1	1.50	m	
2	구	관로구 누수				1	1.00	EA	
3	신	관로구 복원작				1	1.00	EA	
4	신	포장량상관별	2.10	10.0		1	21.00	m ²	
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									
34									
35									
36									
37									
38									
39									
40									
		용역명							
표 례	균열	망상균열	재료분리 2023년 경기북부 송전전력구, 맨홀 정밀안전점검 용역						
	관입공통	박리, 파손							
	누수, 습윤부	배터	참조처 한국전력공사 경기북부본부						
	철근노출	침하							
	강재부식	배수구	용역시 케이아이엠(주)						
	좌굴, 변형	신축이음 본체							

~~운정- 덕이 #7~~

2019.09.20

425

加

◎ 2009 年 10 月 1 日

포장

 $\frac{1}{2}$

④ 망상균열
2.4x9.0

張

서


站

$$0.2 \times 0$$

손상물량표

[illegible]

KEY PLAN




附 錄

	간 없음		마상균열		자료분리
	면칭,공동		백리,피손		시공이음분리, 층분리
	부수,슬출부		낙 태		화적열
	절단노출		점 하		배수구
	강재부식		좌굴,변형		신축이음 분해

용역명	2023년 경기북부 송전전력구, 맨홀 정밀안전점검 용역
발주처	한국전력공사 경기북부본부
발액처	케이아이엠(주)
도면번호	7


문발-운정 #7-1



손상물량표

[illegible]

KEY PLAN



23

	근 입		담당교원		자료분리	용 역 장	2023년 경기북부 순천천리, 만들 정밀안전점검 용역
	편정,공통		박리,파손		상급이음분리, 중요도	참 주 자	
	누수,슬로부		백 태		회차율	용 역 자	케이아이엠(주)
	절근노출		점 하		백수구	도면 번호	8
	강제부식		좌굴,변형		신속이음 본체		

