


KEY PLAN



불광천포장부 J30(OK 872) ~ J35(OK 999)

손상물량표

범례	① - 2013 신규		기① - 기존손상		① 보수원료					비고
	손상위치	적출년도	내용	폭	길이	깊이	물량	단위	개소	
1	30	S	2013	보수원료	1.0	17.0	17.00	m³	1	기존보수
2	30-31	S	2013	망상균열	8.5	6.5	55.25	m³	1	신규
3	31	S	2013	후타재파손	0.8	4.0	3.20	m³	1	신규
4	31-32	S	2013	균열		6.0	12.00	m	2	신규
5	31-32	S	2013	균열	0.5	20.0	20.00	m	1	신규
6	32	S	2013	후타재파손	0.8	7.0	5.60	m³	1	신규
7	32-33	S	2013	망상균열	19.0	4.0	76.00	m³	1	신규
8	33	S	2013	후타재파손	0.8	6.0	4.80	m³	1	신규
9	33-34	S	2013	망상균열	10.0	4.0	40.00	m³	1	신규
10	34-35	S	2013	균열	1.5	10.0	10.00	m	1	신규
11	34-35	S	2013	망상균열	13.0	0.5	6.50	m³	1	신규
12										
13										
14										
15										
16										
17										
18										
19										
20										
21										
22										
23										
24										
25										
26										
27										
28										
29										
30										
31										
32										
33										

-1순위 : Type-7~9 (예일여고~역말사거리)
 -2순위 : Type-9~11 (역말사거리~신사오거리) 및 조인트 손상
 -3순위 : Type-1~7 (시점~예일여고) 및 포장균열

불광지구대

MATCH LINE

STA. OK 872

J-30
마스터자동차

J-31

J-32

J-33
미노르

J-34
상화페인트

J-35

MATCH LINE

신사오거리

영보빌딩

25.0

26.0

26.0

25.0

25.0

127.0

범례



단위

/mm

T=mm

A=mxm

지름

두께

면적

발주처



서울특별시 서부도로사업소

용역사



(주)한국시설안전연구원

PROJECT

불광천1복개 정밀안전진단 및 녹번천복개 정밀점검 용역

TITLE

불광천포장부
J30(OK 872) ~ J35(OK 999)

SCALE

NOTE

0~8