


와 평 교

바닥판 상면 손상현황도

A1 ~ P1(S1)

KEY PLAN

← 간매리



→ 부평리

범례



균열



철근노출



강재부식



백태



누수



파손



박력



열화



재료분리




토사퇴적



들뜸



미세망상



부평리



② 연석 열화
1.0x12.0x2ea

P1

1/7

2/7

3/7

4/7

5/7

6/7

6/6

5/6

4/6

3/6

2/6

1/6

0

A1

1 2

3

4 5

③ 배수구막힘
1ea

① L=0.5

④ 유간부 토사퇴적
L=10.0

⑤ 후타재파손
0.2x0.4



간매리


와 평 교

바닥판 상면 손상현황도


P1 ~ A2(S2)

KEY PLAN

← 간매리



→ 부평리




부평리




② 유간부 토사퇴적
L=10.0

③ 조인트 파손
L=1.0



Ⓐ2



Ⓐ1

① ②

③

④ ⑤



간매리

와 평 교

바닥판 하면 손상현황도

A1 ~ P1(S1)

KEY PLAN

간매리 ←

→ 부평리

범례			
콘크리트	철근노출	강재부식	백태
누수	파손	박락	열화
재료분리	토사퇴적	들뜸	미세망상

부평리

↓ 간매리


와 평 교

바닥판 하면 손상현황도

P1 ~ A2(S2)

KEY PLAN

간매리 ←



→ 부평리

범례



콘크리트



철근노출



강재부식



콘크리트



콘크리트



콘크리트



콘크리트



콘크리트



콘크리트




콘크리트




콘크리트



콘크리트



부평리




간매리

와 평 교

교대 손상현황도


ABUT 1, 2



범 례			
균열	철근노출	강재부식	백태
누수	파손	박락	열화
재료분리	토사퇴적	들뜸	미세망상


- ABUT 1 -

☐	☐	☐	☐	☐	☐
--------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------



- ABUT 2 -




☐	☐	☐	☐	☐	☐
--------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------




와 평 교

교각 손상현황도

PIER 1




전면



좌측

우측



배면