




(구)남한강교 외관조사망도 바닥판 가로보 S13




손상 현황 표

번호	손상 내용	손상 규모			단위	비고
		폭	길이	수량	수량	
1	철근노출	0.1	0.2	1	0.02	m ²
2	철근노출	0.1	0.2	1	0.02	m ²
3	철근노출	0.1	0.3	1	0.03	m ²
4	피손	0.2	0.3	1	0.06	m ²
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						


<CB1>




<CB2>




<CB3>



<CB4>



<CB5>



<CB6>

