

거북교

바닥판 상면 손상현황도

A1 ~ P1(S1)

KEY PLAN

유사리 ←

→ 장흥리

A1

P1

A2

범례

균열

철근노출

강재부식

백태

누수

파손

박락

열화

재료분리

토사퇴적

쓰레기

미세망상

① ② ③ ④ ⑤

장흥리

① 망상균열 4x4.5

P1

1/7 2/7 3/7 4/7 5/7 6/7

6/6 5/6 4/6 3/6 2/6 1/6 0

A1

① ② ③ ④ ⑤

유사리


거북교

바닥판 상면 손상현황도


P1 ~ A2(S2)

KEY PLAN

유사리 ←




→ 장흥리



장흥리



① 망상균열
4x4.5



유사리


거 복 교

바닥판 하면 손상현황도


A1 ~ P1(S1)

KEY PLAN

유사리 ←




→ 장흥리



장흥리



① 철근노출
0.2x0.3x11ea




거 복 교

바닥판 하면 손상현황도

P1 ~ A2(S2)


KEY PLAN

유사리 ←




→ 장흥리

범례



장흥리




유사리

거 복 교

교대 손상현황도


ABUT 1, 2



범 례


균 열	철근노출	강재부식	백 데
누 수	파 손	박 락	열 화
재료분리	토사퇴적	들 음	미세망상

- ABUT 1 -



<유사리 방향>

- ABUT 2 -





<장흥리 방향>


거 복 교

교각 손상현황도

PIER 1




전면



좌측

우측



배면