



주 록 교

교각 손상현황도


PIER 1



① 파손
0.3x0.8




전면



좌측

우측

② 파손
0.2x0.5



배면