


교 리 교

바닥판 상면 손상현황도

P2 ~ A2(S3)

KEY PLAN

가업동 ←



→ 홍문동

범례



콘크리트



철근노출



강재부식



백태



누수



파손



박락



열화



재료분리




토사퇴적




돌움




미세망상



홍문동

② 후타재 균열
0.1/0.2x30ea③ 차수판 탈락
1ea

A2



6/6

5/6

4/6

3/6

2/6

1/6

0

P2

① ②

③

④ ⑤



가업동