


삼 교 교

바닥판 상면 손상현황도

A1 ~ P1(S1)



KEY PLAN

← 가업동



→ 홍문동

범례



홍문동



① 연석 열화
0.5x13.0x2ea

(P1)

1/7 2/7 3/7 4/7 5/7 6/7

6/6

5/6

4/6

3/6

2/6

1/6

0

③ 난간파손
L=2.0

② 배수구막힘
2ea

(A1)

① ②

③

④ 유간부 토사퇴적
L=10.0

④ ⑤

⑤ 후타재 열화
0.6x10.0



가업동