


삼 교 교

바닥판 상면 손상현황도

P1 ~ P2(S2)



KEY PLAN

가업동 ←



→ 홍문동

범례



홍문동



① 연석 열화
0.5x13.0x2ea

P2

1/7

2/7

3/7

4/7

5/7

6/7

6/6

5/6

4/6

3/6

2/6

1/6

0

P1

1 2

3

4 5

② 배수구막힘
2ea



가업동