


장풍제2교

바닥판 상면 손상현황도

P1 ~ A2(S2)

KEY PLAN

후포리 ←



→ 장풍리

범례



균열



철근노출



강재부식



백태



누수



파손



박락



열화



재료분리




토사되적



들뜸



미세망상



장풍리



① 유간부 토사되적
L=11.0

② 후타재 망상균열
1.0x11.0

(A2)



6/6

5/6

4/6

3/6

2/6

1/6

0

(P1)

① ②

③

④ ⑤



후포리