


하 동 교

바닥판 상면 손상현황도

A1 ~ A2(S1)

KEY PLAN

← 가업동



A1 A2

→ 홍문동

범례



콘 열



철근노출



강재부식



백 데



누수



파손



박락



열화



재료분리




토사퇴적



돌음



미세망상



홍문동



1/7

2/7

3/7

4/7

5/7

6/7

③ 유간부 토사퇴적
L=15.0

6/6

A2

① 파손 및 철근노출
0.3x0.5

5/6

4/6

3/6

2/6

1/6

0

A1

1 2

3

4 5

④ 유간부 토사퇴적
L=15.0



가업동