


가 마 교

바닥판 상면 손상현황도

P2 ~ A2(S3)


KEY PLAN

가업동 ←




→ 홍문동

범례			
	균열		철근노출
	강재부식		백태
	누수		파손
	재료분리		박락
	토사퇴적		열화
			미세망상



홍문동



A2

6/6

6/7

5/7

4/7

3/7

2/7

5/6

4/6

3/6

2/6

1/6

P2

0

5 4

3

2 1

중조인트



가업동