


새 터 교

바닥판 상면 손상현황도

P2 ~ A2(S3)


KEY PLAN

← 가업동



→ 홍문동

범례			
균열	철근노출	강재부식	백태
누수	파손	박락	열화
재료분리	토사퇴적	돌출	미세망상




홍문동



1/7 2/7 3/7 4/7 5/7 6/7

A2



6/6

5/6

4/6

3/6

2/6

1/6

0

P2

1 2

3

4 5



가업동