

옹벽 상태 진단 결과표

1. 시설물명 : 하남역CY장옹벽
 2. 위치 : 광주광역시 광산구 임곡동
 3. 옹벽종류 : 콘크리트옹벽
 4. 스펀의 갯수 : 32

No.	첨 하	계획선형오차	활동	세굴	파손 및 손상	균열	마모 /침식	박리	침강 및 층분리	백태	철근 노출	중성화	염화물	배수공	주변영향인자				평가단위 결함지수	평가단위 평가등급
						이격	유실	침강 상태		진행성 변형					배수 시설	사면조사				
																사면 구배	낙석 흔적	침출수		
1	0	0	0	0	2	6	0	1	0	0	0	0	0	3	0	0	0	0	0.164	B
2	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
3	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
4	0	0	0	0	0	0	0	1	2	0	0	0	0	3	0	0	0	0	0.082	A
5	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
6	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
7	0	0	0	0	0	0	0	1	0	0	0	0	0	3	0	0	0	0	0.055	A
8	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
9	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
10	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
11	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
12	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
13	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
14	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
15	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
16	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
17	0	0	0	0	0	2	0	0	0	0	0	0	0	3	0	0	0	0	0.068	A
18	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
19	0	0	0	0	0	0	0	1	1	0	0	0	0	3	0	0	0	0	0.068	A
20	0	0	0	0	0	0	0	0	2	0	0	0	0	3	0	0	0	0	0.068	A
21	0	0	0	0	0	0	0	1	0	0	0	0	0	3	0	0	0	0	0.055	A
22	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
23	0	0	0	0	0	0	0	0	1	0	0	0	0	3	0	0	0	0	0.055	A
24	0	0	0	0	0	0	0	1	0	0	0	0	0	3	0	0	0	0	0.055	A
25	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
26	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
27	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
28	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
29	0	0	0	0	0	0	0	1	0	0	0	0	0	3	0	0	0	0	0.055	A
30	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	0	0	0.041	A
31	0	0	0	0	0	0	0	1	1	0	0	0	0	3	0	0	0	0	0.068	A
32	0	0	0	0	0	0	0	0	1	0	0	0	0	3	0	0	0	0	0.055	A
평균	-	-	-	-	0.1	0.8	-	0.3	0.3	-	-	-	-	3.0	-	-	-	-	0.060	

상태평가등급

A