





10. 보강토옹벽(4공구)




정면도(VIEW "A")



단면 K-K



단면 M-M



단면 N-N

(주)위드이앤오

Project Title
2017년 상반기 시설물 정기점검 용역

Drawing Title
보강토조립식옹벽(4공구) 정면도 및 단면도

Note

ID:4공구 보강토 조립식 옹벽(1)

보 수 이 력		
<u> </u>	기 존 규 열	<u>19</u> 보 수(12. 상반기)
<u> </u>	신 구 규 열	<u>10</u> 보 수(12. 하반기)
<u> </u>	보수부위재검열	<u>11</u> 보 수(13. 상반기)
<u>1</u>	보 수(기보수)	<u>12</u> 보 수(13. 하반기)
<u>2</u>	보 수(08. 하반기)	<u>13</u> 보 수(14. 상반기)
<u>3</u>	보 수(09. 상반기)	<u>14</u> 보 수(14. 하반기)
<u>4</u>	보 수(09. 하반기)	<u>15</u> 보 수(15. 상반기)
<u>5</u>	보 수(10. 상반기)	<u>16</u> 보 수(15. 하반기)
<u>6</u>	보 수(10. 하반기)	<u>17</u> 보 수(16. 상반기)
<u>7</u>	보 수(11. 상반기)	<u>18</u> 보 수(16. 하반기)
<u>8</u>	보 수(11. 하반기)	<u>19</u> 보 수(17. 상반기)


손상 현황 표

[illegible]

주) 손상의 폭과 길이는 m 이며, 단 균열의 폭은 mm 임


부산 ←

→ 대구




KEY PLAN

The key plan shows the site layout with the proposed building (101750.433) and the existing building (101654.733). The proposed building is located at the top right, and the existing building is at the bottom left. The site is bounded by a road to the north and a road to the east. The proposed building is situated on a plot of 16,100 square meters, and the existing building is on a plot of 20,000 square meters. The site is divided into two main sections by a road. The proposed building is located on the northern section, and the existing building is on the southern section. The site is bounded by a road to the north and a road to the east. The proposed building is situated on a plot of 16,100 square meters, and the existing building is on a plot of 20,000 square meters. The site is divided into two main sections by a road. The proposed building is located on the northern section, and the existing building is on the southern section.



SECTION

Architectural section drawing showing a sloped roof structure with a vertical section cut. The roof is labeled with a slope of 1:1.5. The building's exterior is indicated by a dashed line. The interior structure includes a series of horizontal layers, with labels indicating the thickness and material of the roof and floor slabs: 50 X8 8000 C.T.C. and 100 X8 8000 C.T.C. A small detail of a door or window is shown at the bottom left.



용역명	2017년 상반기 시설물 정기점검 용역
과업기간	2017. 03. 21 ~ 2017. 06. 30
발주처	 신대구부산고속도로주식회사
용역사	(주)위드이앤오
도면번호	001

10:4공구 보강토 조립식 옹벽(2)


보 수 이 력		
<u> </u>	기 존 규 열	<u>19</u> 보 수(12. 상반기)
<u> </u>	신 구 규 열	<u>10</u> 보 수(12. 하반기)
<u> </u>	보수부위재검열	<u>11</u> 보 수(13. 상반기)
<u>1</u>	보 수(기보수)	<u>12</u> 보 수(13. 하반기)
<u>2</u>	보 수(08. 하반기)	<u>13</u> 보 수(14. 상반기)
<u>3</u>	보 수(09. 상반기)	<u>14</u> 보 수(14. 하반기)
<u>4</u>	보 수(09. 하반기)	<u>15</u> 보 수(15. 상반기)
<u>5</u>	보 수(10. 상반기)	<u>16</u> 보 수(15. 하반기)
<u>6</u>	보 수(10. 하반기)	<u>17</u> 보 수(16. 상반기)
<u>7</u>	보 수(11. 상반기)	<u>18</u> 보 수(16. 하반기)
<u>8</u>	보 수(11. 하반기)	<u>19</u> 보 수(17. 상반기)

손상 현황 표

[illegible]

주) 손상의 폭과 길이는 m 이며, 단 균열의 폭은 mm 임

→ 대구



KEY PLAN

보행자 조형식 광복 시공

측량 : 10H756-433

보행자 조형식 광복 시공

측량 : 10H854-733

SECTION

1.15

1.18

50 KN 5000 C.T.G.

50 KN 5000 C.T.G.

50 KN 5000 C.T.G.

100 KN 5000 C.T.G.

용역명	2017년 상반기 시설물 정기점검 용역
과업기간	2017. 03. 21 ~ 2017. 06. 30
발주처	 신대구부산고속도로주식회사
용역사	(주)위드이앤오
도면번호	002

10:4공구 보강토 조립식 옹벽(3)


보수 이력			
	기 존 규 역		보 수(12. 상반기)
	신 규 규 역		보 수(12. 하반기)
	보수부위재균열		보 수(13. 상반기)
	보 수(기보수)		보 수(13. 하반기)
	보 수(08. 하반기)		보 수(14. 상반기)
	보 수(09. 상반기)		보 수(14. 하반기)
	보 수(09. 하반기)		보 수(15. 상반기)
	보 수(10. 상반기)		보 수(15. 하반기)
	보 수(10. 하반기)		보 수(16. 상반기)
	보 수(11. 상반기)		보 수(16. 하반기)
	보 수(11. 하반기)		보 수(17. 상반기)

손상 현황 표


[illegible]

주) 손상의 폭과 길이는 m 이며, 단 균열의 폭은 mm 임

KEY PLAN



SECTION



용역명	2017년 상반기 시설물 정기점검 용역
과업기간	2017. 03. 21 ~ 2017. 06. 30
발주처	 신대구부산고속도로주식회사
용역사	(주)위드이앤오
도면번호	003